

No.	Name	Qty
1	M10 Crossbite Nuts	1
2	On Protective cover	1
3	On the plate	1
4	Lower platen	1
5	Ø 32 Hole Collar	1
6	6002 Closed said axis	1
7	Splined shaft	1
8	Spline teeth	1
9	6000 Closed said axis	3
10	Under the protective cover	1
11	M5*12 Combination screw	2
12	Gearbox	1
13	Bevel Gear	1
14	Ø 10 Shaft Collar	1
15	Ø 26 Hole Collar	1

